PATENT APPLICATION

HEWLETT-PACKARD COMPANY Intellectual Property Administration P.O. Box 272400 Fort Collins, Colorado 80527-2400

ATTORNEY DOCKET NO. ___

10011155 -1

Inventor(s):

Kurt Spears et al

Application No.: 09/780984

Filing Date: Feb

Feb 09, 2001

Confirmation No.: 2245

Examiner: Gabriel Garcia

Group Art Unit: 2625

Title: Controller For Photosensor Array With Multiple Different Sensor Areas

Mail Stop Commissioner For Patents PO Box 1450 Alexandria, VA 22313-1450

TRANSMITTAL LETTER FOR RESPONSE/AMENDMENT

No additi								Suppl	emental		
X Other C	Certificate of Correction CLAIMS AS	AMENDE	D BY O	THER	ΤΗΔΝ Δ	SMA	ALL EN	JTITY	Fee	÷\$	0
(1) FOR	(2) CLAIMS REMAINING AFTER AMENDMENT	(3) NUMBER EXTRA	(4) HIGHEST NUMBER PREVIOUSLY PAID FOR			(5) PRESENT EXTRA		(6) RATE		(7) ADDITIONAL FEES	
TOTAL CLAIMS		MINUS				=	0	х	\$52	\$	0
INDEP. CLAIMS		MINUS				=	0	х	\$220	\$	0
FIRST PRESENTATION OF A MULTIPLE DEPENDENT CLAIM + \$390										\$	0
EXTENSION FEE	1st Month \$130		2nd Month \$490		3rd Month \$1110			4th Month \$1730		\$	0
				•			(OTHE	R FEES	\$	0
		Т	OTAL AD	DITIC	NAL FEE	FOR	THIS A	MEN	DMENT	\$	0

Charge \$_____ to Deposit Account 08-2025. At any time during the pendency of this application, please charge any fees required or credit any over payment to Deposit Account 08-2025 pursuant to 37 CFR 1.25. Additionally charge any fees to Deposit Account 08-2025 under 37 CFR 1.16 through 1.21 inclusive, and any other sections in Title 37 of the Code of Federal Regulations that may regulate fees. A duplicate copy of this sheet is enclosed.

Respectfully submitted,

Kurt Spears et al

Jeff D. Limón

Attorney/Agent for Applicant(s)

Reg No.: 45,418

Date: 3/24/2009

Telephone: 541 715 5979

Rev 10/08 (E-TransAmd)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO

: 7,349,129

APPLICATION NO.: 09/780,984

ISSUE DATE

: Mar. 25, 2008

INVENTOR(S)

: Kurt E. Spears, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 11, line 15, delete "Lo" and insert - - to - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACKARD COMPANY Intellectual Property Administration P. O. Box 272400 Fort Collins, Colorado 80527-2400

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.

IN THE UNITED STATES PATENT & TRADEMARK OFFICE

IN RE APPLICATION OF: U.S. Patent No. 7,349,129 **USPTO CONFIRMATION CODE: 2245** APPLICATION NO.: 09/780,984 FILED: Feb. 09, 2001 **EXAMINER:** Gabriel Garcia **GROUP ART UNIT: 2625** FOR: CONTROLLER FOR PHOTOSENSOR ARRAY WITH MULTIPLE DIFFERENT SENSOR AREAS ATTORNEY DOCKET NUMBER: 10011155-1 37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS Sir: The following is a request for a certificate of correction in Serial Number 09/780,984, now Patent Number 7,349,129. A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent. All errors were the fault of the USPTO, no fee required. In the event that a further fee is required, please charge the amount to Deposit Account No. 082025. All errors were the fault of the applicant and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

is required, please charge the amount to the same Deposit Account.

The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee

In column 11, line 15, delete "Lo" and insert - - to - -, therefor. (Specification filed on Feb. 09, 2001, page 16, line 5)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

3/24/2009 DATE

Name: Jeff D. Limón Registration No.: 45,418

Attorney/Agent of Record